

Memorandum for the Granger Record

9 Dec 58

25X1

On 9 Dec 58, a phone call was received from Commander [redacted]. He said that Mr. [redacted]

25X1

25X1

[redacted], the Navy "break-lock" device expert, had a long talk with Mr. [redacted] concerning the Granger Mod 504. It is Mr. [redacted] opinion

25X1

25X1

that the primary trouble is a lack of power. He made some suggestions on how to increase the power output with very little cost in weight. Mr. [redacted] is to go to [redacted]

25X1

25X1

25X1

Tonight armed with questions from Mr. [redacted]

He should have the answers back by Friday, and Cmdr [redacted] will try to arrange for a round table discussion at that time.

25X1

25X1

25 YEAR RE-REVIEW